



Natural Disaster Supplemental

U.S. AIR FORCE

The Air Force requires \$1.2B in FY2019 and \$3.7B in FY2020/FY2021 of supplemental funding to rebuild Tyndall AFB, and recover Offutt AFB. **Without supplemental funding now, the Air Force must cut critical facility and readiness requirements, driving Air Force wide operational risks and negatively impacting the recovery of Tyndall and Offutt.**

FY19 Immediate Need

Tyndall:

Operations & Maintenance:
~\$750M FSRM & Support

Military Construction:
~\$150M Planning & Design

Offutt:

Operations & Maintenance:
~\$350M FSRM & Support

FY 2020 Needs

Tyndall:

Operations & Maintenance:
~\$893M FSRM & Support

Military Construction:
~\$2,534M Construction

Offutt:

Requirements: TBD

Future Needs

Tyndall:

Procurement:
~\$127M Equipment

Actions & Impacts Without Supplemental

1) Stop Facility Repairs Air Force Wide: Defers 61 required facility projects at bases in 18 states across the U.S., impacting airfields and critical base facilities.

2) Stop Tyndall Recovery: Stops all new work on Tyndall as of 1 May; delays the return of full base operations, severely impairs flight operations and forces personnel to continue to work in degraded facilities.

3) Cut Aircraft Repairs: Curtails aircraft repairs starting 15 May, grounds five bomber aircraft as early as Sep 2019, and creates long-term backlog for the E-3 aircraft maintenance.

4) Limit Offutt Recovery: Beginning 1 July, defers all Offutt recovery efforts, with the exception of immediate health and safety needs; delays facilities assessment and mitigation efforts, increasing damage from mold and water.

5) Cut Flying Operations: Cuts 18,000 training flying hours starting 1 September, slowing our readiness recovery.

Risk Timeline



Please direct any questions to SAF/LL (703-697-4142) or SAF/PA (703-697-6061)

Installation	State/Country	Project Title
Cape Lisburne	AK	Repair Building Foundation (B151)
Cape Lisburne	AK	Repair Building Foundation (B151)
Davis Monthan	AZ	RED HORSE - Construct SFS Mobility Storage
Davis Monthan	AZ	Repair Runway 12/30
Beale	CA	Repair 4 Bridge System, Gavin Mandery Drive
Vandenberg	CA	Replace OH Distribution Line B10, Bldg 81201
Vandenberg	CA	Repair CRAC Units & Chiller, Bldg 12000
Buckley	CO	Repair by Replace HVAC Systems B430, Space Ops Fac
Buckley	CO	Repair by Replace Emergency Generators, B433
Cheyenne Mtn	CO	Repair Auxiliary Air Intake Blast Valve Hoists
Peterson	CO	Demo Site FAMCAMP Support
USAF Academy	CO	Rpr Cadet Chapel
USAF Academy	CO	Sust/Rpr Runways/Taxiways FY19
Eglin	FL	Renovate SAPF Bldg. 1318
MacDill	FL	AAFES APF Companion Project B926
MacDill	FL	Rpr HVAC & Renovate COMM Fac B262
Ramstein	Germany	REPAIR HVAC COMM FAC. 496
Ramstein	Germany	Add/Alt Fire Station #1
Ramstein	Germany	DSN-APF SUPPORT RAMSTEIN MS MILCON
Kadena	Japan	CONSTRUCT ENTRY CONTROL FACILITY
Kadena	Japan	CONSTRUCT ALLIED SUPPORT FOR PAINT BOOTH, B3555
Kadena	Japan	REPAIR AIRCRAFT CORROSION CONTROL VENTILATION
Kunsan	Korea	REPLACE HVAC SYS, SUPPLY WAREHOUSE B823
McConnell	KS	REPAIR (R&M) COMMAND POST BLDG 1107
Barksdale	LA	DSN - Renovate Dorm 4323
Barksdale	LA	Repair Hgr Maint Dock B6628 Doors
Hanscom	MA	Rpr (Replace) Emergency Generator, HQ Center, B1612
Hanscom	MA	Demolish Lab Facilities, Multi
Hanscom	MA	Gate 2 Demolish Visiting Officer Quarters (VOQ) B-1426
Hanscom	MA	RPR (RENOVATE) MCS, B1709E
JB Andrews	MD	REPAIR BUILT-UP ROOFS BLDGS 1734, 1241, 1560, 1889,
JB Andrews	MD	DSN ADD/ALTER ATFP VA GATE
Columbus	MS	REPAIR AIRFIELD/TAXIWAY ALPHA DRAINAGE
Columbus	MS	REPAIR PERIMETER ROAD EAST
Keesler	MS	Gate Entry Road
Malmstrom	MT	CSN-Repair Missile Field Fuel Systems IDIQ-B11
New Boston	NH	Repair Roof, Bldg. 157
Kirtland	NM	Repair AVB System, Eubank Gate
Wright Patterson	OH	RENOVATE/CONSOLIDATE 88 CES F/30015 (COMPANION
Wright Patterson	OH	REPAIR CONDENSER WATER SYSTEM AFRL F/20651 &
Tinker	OK	REPAIR HVAC SYSTEM MAIN FIRE STATION, B117
Tinker	OK	REPAIR HVAC SERVING TELECOM FACILITY B3001G
Tinker	OK	REPAIR SURFACE GRADE AT CDC EAST, B3904
Tinker	OK	REPAIR SURFACE GRADE CDC SOUTH, B1101 (RAC4)
Lajes	Portugal	Demolish T-717 and Construct T-715 Parking Lot
JB Charleston	SC	REPAIR (COMP TO NAVY)(SUS) PIER XRAY
JB Charleston	SC	Repair (SUS)HVAC System NPTU, B2314
Dyess	TX	Repair/Replace Hangar Door & Supporting System
Dyess	TX	Repair/Renovate SCIF, 8031
Dyess	TX	Renovate Dorm, 6113
Dyess	TX	Renovate Dorm, 6112
Goodfellow	TX	PCR - Add/Alter Fire Station, B3321
Goodfellow	TX	Construct Dry Fire Trainer
Goodfellow	TX	REPAIR EXISTING LIGHTS, POLES, WIRE
JBSA-Lackland	TX	Repair Renovate RHT Barracks, B9110
Laughlin	TX	RENOVATE ATCAL5, B820
Laughlin	TX	ALLIED SUPPORT T-1 SUNSHADES
Sheppard	TX	Repair Chillers & Controls, B1951
RAF Lakenheath	United Kingdom	RPR VAULT, F-35, B1346
RAF Lakenheath	United Kingdom	RPR MUNS ADMIN, F-35, B1494 AND 1495
Hill	UT	Repair East 388th 419th FW Apron - Fac 5000